QUALITY CONTROL

Name of the Work:	Improvements of Roads and drains at Maheshwarinagara & Kempegowda Nagara 6th 'B' cross A/S in dasarahalli W. NO-15
Job No:	015-13-000038
Work order No:	133/13-14 D: 4-9-2013
BR No:	459/13-14 D: 31-10-13

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

31/5/15

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike